FIG.1




FIG.2




FIG.3A







FIG.3B











FIG.7








FIG.9




FIG.10




FIG.11




FIG.12





FIG.13






FIG.14B




FIG.14C




FIG.14D






FIG.14E









RATIO OF LARGE-DIAMETER POWDER(%)

FIG.16



RATIO OF LARGE-DIAMETER POWDER(%)

FIG.17






FIG.19

